



Contaminants

Soil and stream contaminants include antimony, arsenic, cadmium, iron, lead, manganese, benzo(a)anthracene, and benzo(b)fluoranthene.

Water contaminants above applicable standards include copper, nickel, and zinc.






- -Quarterly Community Clean Up -Bi-monthly community meetings
- -Ongoing remediation options with NC DEQ

GET INVOLVED Sohnie Black Community Advocate stblack@uncg.edu

336 965 7200

BINGHAM PARK NO TRESPASSING DUSK TO DAWN







Nev Incinerator. e Greensboro city council decida meeting Friday to locate the incinerator between the convioon the northweet side of Green cemetery and the creek. It will \$15,667.

's New Incinerator To Be On South Buffalo

e new city incinerator is to be ted on South Buffalo creek, t. three-quarters of a mile from ity limits, at a cost of approxily \$20,000, and will be comand modern in every respect. e decision was reached by the council Monday afternoon by a vote. Mayor Kieer. -to-two te A. Grimsley and R. G. Hiatt in favor of the South Buffile and Frank A. Brooks, and D'-White voted against it. E. J. Price denhall and Julian A. not present, but it is underthat Mr. Price was for it and Mendenhall against it.

INDIGNANT OVER INCINERATOR SIT

Citizens of South Greensboro Dr Up Resolutions Opposing Incinerator On South Buffalo

Between 300 and 400 people r in the South Buffalo schoolho Tuesday night in an indignat meeting over the steps taken by city council towards placing an cinerator on South Buffalo creek. The body assembled emphatics declared that the plan of the o council was a decided injustice the people of South Greensboro. petition was circulated Tuesday ernoon and met with favor in ev part of South Greensboro. The w en are greatly opposed to the co cil's plans, and resolved to do they can to have the proposed changed.

Resolutions were adopted to presented to the city council on M day afternoon, asking the city o missioners to reconsider their cision to place the incinerator South Buffalo.

The Hampton Elementary School

Hampton Elementary was built in 1960, just a couple of years after the incinerator shut down

Hampton Elementary School was severely damaged in a tornado in 2018.

Officials announced that it will not be rebuilt due to environmental concerns.



1922 Incinerator Site Opposition

1922: City Council of Greensboro announced its plan to construct a new incinerator on the South Buffalo Creek.

1922: South Greensboro petitioned against the decision, 300 to 400 people, mainly women, met in local schoolhouse to oppose.



Proposed Remedy by the Department of Environmental Quality

- Grading
- Installation of geotextile
- Installation of geoweb
- Infilling geoweb with soil